COUNTRY	GermanApp			2006/03/17 : CIA <sub>2</sub> RDP82-		0001-1	
TOPIC	Oranienbu			CONFIDENTIAL	REPORT	Mill	/_
<b>等等等等的地位的</b> 表示,不要不 <b>可能</b> 的点点	metinkennettetummenter un 1. mengana	CONTRACTOR OF THE CONTRACTOR O		The second secon	and the second of the second s	1/02	1
EVALUATION		2	25X1 <sub>PI</sub>	ACE OFTAINED 25X1		25X1	TO SETE PROBLEMS
DATE OF CO	итеит.			25X1	PRINT SSS TOTAL COMMANDE STATE OF THE SSS TOTAL COMMANDS	The second secon	Consider york it. The Committee Confidence of
DATE OBTAIN	NED_			DATE PREPAREZ	19 June 1951		***************************************
REFERENCES	S			25X1	The state of the s		
PAGES_2_	. and the second se	NCLOSURE	S (NO. &	TYPE)	ella Sapra inno rivosa de caso di anticistado e distinguismo calcistando, comangen amengan que por		and the second
REMARKS				and the second section of the section o	enter som en	Control to the second s	Life WAY HARMONING STORY
**************************************	der die statische Wastermittel der statische der der der der der der der der der de		Protective Physical Residence of Security (	mentioner/Philippingersker kelskhalleren-mikkel, för tru desse leks salakkenskal av de	MICK CO. P. COST. AND PROCESSOR AND PROCESSO		THE RESERVE OF THE PERSON NAMED IN
444003 Million Brook 201 Review November (2004 Inc. Orbit Anni Albania)	orareactives countries and market companies are a	- Control of the second se		en e	diska i make, reastate diservita j raksam jemesteve i sada ja		
25X1 25X1 25X1 3.	cloudy. For convention A core was the jet bo door. (2)  On 10 May south of t planes were and there twin-jet be number were silve.  Flying was	Fourteen all bombes distincts between the hangare aloft. was an ordanes had and the open of the control of the	jet bombers were control were two vereast and a blist leading me rudder	1951, there was fly wind one northeasterly winders in addition to an observed at the field gnized in the air interestined blister was retical slots at the retical slots at the rest and 12:30 p.m., 10 lemburg airfield. And was a northeasterly was a northeasterly was an altitude of appear on the underside edge of wing. One of assembly forward of the contract of the	takes of the tweet of the fer rear of the fer undetermined wind, visibility of the fuselage of the planes of the Soviet st	twin-engine  to engines of the nose wheel uselage.  s were observed number of other y was about 3 km on meters. The e, between the as marked with ar. The planes	urg
i i	clouds, (3) were also in most can Alter refu- southern en high-pitche 15 seconds sound. About Trun; in average any for landing refueled. ties the De irregularly was about 1	) By noo practicing ses from cling, the nd of the ed whistl. When to out 60 per none case about 8 about 8 However, umbo type y, counte 25 second	on, the 1 or flying two tenk planes runway. e for ab the plane recent of e only a imb was o percen their c radar s r-clockw s.	one of the planes we. O planes which had to. Prior to the take trucks, one being planed individually Frior to the take out 15 seconds and to seconds and to seconds and to seconds and to second to the length of the report of the length of the result 100. There was one tof the runway was rews were not change et at the northeaste ise. The average du CONFIDENTIAL	me flying in o een parked sou e-off these pla arked in front to the take-of off, the plane hema loud rea roar changed in unway was need he runway was in take-off every used. After 1 d. During the programmer of the ration of one	r above the th of the hangar uses were refucled of each engine. If point at the s produced a refer enother nto a whistling ed for the take- needed. (4). The three minutes. anding the planes flying activi-	
and a second particle attention and the or an experience and the second attention at the second attention attention at the second attention at the		CLASSIFICA	NOITA	CONTRA /US OFFI	CIALS ONLY	. The state of the	<b>Marrie</b> s Saintle Millions of a sainteenfe and a
		Rs € □ 0 €lass.	meat No. hange in ( sclassified Changed Hill To.	Hass. 25X1			

## Approved For Release 2006/03/17 : CIA-RDP82-00457R008100220001-1 CONFIDENTIAL

CONTROL/US OFFICIALS ONLY

25X1

type practiced flying.	No flying was observed on 11, 15 or 16 May. On the afternoon of 17 May, 10 twin-jet planes were observed parked in one line south of the hangar.	25X
	The state of the s	

6. At hill p.m. on 17 May, the two planes mentioned in the preceding paragraph took off at intervals of 30 seconds and headed north. At the northern edge of the field the two planes had reached a height of about 40 meters and were climbing into the clouds. At h:55 the two planes flew over the field side by side at an altitude of about 700 meters. This was repeated at 5:05 p.m. The two planes landed at 5:10 p.m. at 30 seconds interval and then taxied to the western side of the parked aircraft. Three men left the plane through the bottom and three other men boarded the plane. (5) Refueling was not observed. The activity mentioned above was repeated from 5:25 to 5:50 p.m. From 50 to 60 percent of the runway was needed for the take-off run and about 80 percent for the landing.

- On 11 May 1951, five-twin-engine jet bombers were seen flying over Oranienburg at a high altitude. On 14 May between 10 and 11 plm., night flying with jet bombers was observed for the first time from a point about 5 km northeast of Oranienburg.(3) Three planes flew over source's position at intervals of 25X1 & to 10 minutes. Although the planes flow without landing lights their type could be determined from the familiar noise they produced.
  - 9. On 17 May 1951, between 9 a.m. and noon there was unusually heavy flying. The jet bombers were flying in flight formation at an estimated altitude of 1,000 meters, the ceiling being about 1,200 meters.

25X1 Comments. The number of type 27 planes stationed at the field is unknown. While more than 30 such planes were observed at the field prior to 5 May 1951, several sources concordantly stated that they saw only 10 to 14 type 27 planes after 10 May 1951. The whereabouts of the other planes is not known. The PE-2s previously stationed at the field are believed to be still there.

(2) The purpose of the blister had not yet been determined. It is likewise unknown how many of the planes stationed in Oranienburg are fitted with such a blister. Two sources observed that the crew members boarded the plane through the bottom.

25X1

(3) These observations and the information contained in paragraph 8 of the present report indicate that type-27 planes are fitted with night flying instruments and that the crews of these planes have undergone training for instrument flying with this type of aircraft.

(4) Since the runway at Oranienburg airfield is 2,100 meters long, the length

of the take-off run would therefore be 1,200 to 1,300 meters.

25X1<sup>25X1</sup> the plane had a crew of five. 25X1

CONFIDENTIAL

CONTROL/US OFFICIALS ONLY